



**VOLKSWAGEN Crafter 35 LWB HR: 1BVW065**

Vinnumber:	<b>WV1ZZZ2EZB6023585</b>	Versionname:	<b>CRAFTER 35 B/F LWB HR 109pk</b>
First Registrationdate:	<b>16/09/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>184208</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV16</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>No GPS</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>No climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/65/16/113 R Steel</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1176,69</b>
-------------------	----------------

Wing R R, Rust, Acceptable	<b>0,00</b>
----------------------------	-------------

*No pictures to display*

Bumper corner R R, Scratch(es), Smart repair	<b>110,64</b>
--	---------------



Wing(s), Rust, LI - Repair and paint (complete)



Sill outer R, Rust, LI - Repair and paint (complete)

232,88



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

471,15



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display