


FORD Fiesta: 1ETY919

Vinnumber:	WF0DXGAKDDM76830	Versionname:	FIESTA BER Trend DPF 75PK SPECIMEN
First Registrationdate:	20/03/2013	Fiscalpower:	
Expertise Mileage:	226862	Power Kw:	55
Bodytype:		Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3425
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
GPS storage			
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/50/15/82 H Steel				
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	0,00
-------------------	------

Tyre F R, Not original part, Acceptable	0,00
---	------

No pictures to display

Rearview mirror housing R, Scratch(es), 67 - Polish	0,00
---	------

No pictures to display

Bumper F, Dent(s) and scratch(es), Acceptable	0,00
---	------



Bonnet, Stone chip(s), Acceptable 0,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Wing F L, Chemical polution, 67 - Polish 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 0,00




Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00





Roof, Chemical polution, LI - Repair and paint (complete)

0,00



Reflector, Broken, E - Replace

0,00



Door R R, Scratch(es), LI - Repair and paint (complete)

0,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

0,00





Rear spoiler, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display