



RENAULT Trafic: 1FCE273

Vinnumber:	VF1FLA0AEDV437878	Versionname:	TRAFIC 27 B/F L1H1 Confort FAP(E5)90PK
First Registrationdate:	22/05/2013	Fiscalpower:	
Expertise Mileage:	177818	Power Kw:	66
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3213
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	OK	Sound engine	OK
Exhaust gass	OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/16/92 H Steel				
Summer tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 2895,47

Trunk door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 250,00



Interior, Damaged, Acceptable 0,00



Bumper R, Dent(s) and scratch(es), E - Replace 329,40



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 304,88



Maintenance, Maintenance, Execute 0,00

No pictures to display

Steering wheel, Worn, Acceptable 0,00



Backrest cover F L, Bad repair, E - Replace 0,00



Sidewall FR (LCV), Dent(s) and scratch(es), LI - Repair and paint (complete) 150,00



Bumper F, Dent(s), E - Replace 398,40



Sidewall RL (LCV), Dent(s) and scratch(es), LI - Repair and paint (complete) 300,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 280,88



Seat cover F R, Burned, Smart repair

64,32



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Wheel cover R L, Missing, E - Replace

22,50



Rearview mirror housing R, Scratch(es), Smart repair

110,64



Trunk door R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)

165,13



Instrument panel complete, Broken, E - Replace

15,00



Sidewall RR (LCV), Dent(s) and scratch(es), It - Spot repair

115,56



Ignition key, Missing, E - Replace

150,00

No pictures to display