



**BMW 1 HATCH: 1TCS259**

Vinnumber:	<b>WBA1V51020V998931</b>	Versionname:	<b>114d (70 kW)</b>
First Registrationdate:	<b>26/09/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>55113</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2410</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/94 V LightMetal</b>			
Winter tyres:	Fr.L.	Fr.R.	Michelin: 6 mm
	Re.L.	Re.R.	Michelin: 4 mm

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>3078,90</b>
<b>Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>318,35</b>



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00




Covering interior A pillar L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Door F L, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Wing R L, Scratch(es), 67 - Polish

0,00

*No pictures to display*

Alloy rim F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Door panel R L, Scratch(es), Smart repair

110,64



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00




Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 366,35



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Rear window, Scratch(es), E - Replace 370,00

