



RENAULT CLIO: 1LPG928

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber: | VF15R0J0A54118296 | Versionname: | 1.5 ENERGY DCI 90E EXPRESSION |
| First Registrationdate: | 4/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 95312 | Power Kw: | 66 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2115 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Windows electric F | Luggage cover |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 185/65/15/92 H Steel | | | |
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------|
| Total cost ex VAT | 1208,56 |
|-------------------|---------|

| | |
|--|--------|
| Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) | 115,56 |
|--|--------|



Wheel cover F R, Missing, E - Replace



Wheel cover R L, Scratch(es), Acceptable

0,00



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

24,00



Wheel cover F L, Scratch(es), E - Replace

24,00



Bumper R, Crack, Le - Replace and paint

535,20



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), It - Spot repair

115,56



Door R R, Scratch(es), LI - Repair and paint (complete)

254,68



Roof pillar L, Scratch(es), Acceptable

0,00

No pictures to display