


OPEL ZAFIRA TOURER: 1LRZ269

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WOLPE9E36G1032574 | Versionname: | 1.6 CDTI ECOFLEX 100KW S/S COSMO |
| First Registrationdate: | 18/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 123639 | Power Kw: | 100 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | UITVOEREN | Parking lot: | 4528 |
| Maintenance: | NOT OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| GPS storage | | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 225/50/17/94 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Uniroyal: 6 mm | Fr.R. | Uniroyal: 6 mm |
| | Re.L. | Uniroyal: 7 mm | Re.R. | Uniroyal: 7 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--|---------|
| Total cost ex VAT | 1322,95 |
| Electricity circuit, Not functioning (well), P - Check | 0,00 |



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Seat cover F L, Worn, Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), It - Spot repair

115,56



Floor covering F L, Hole, Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Stain, Cleaning

25,00



Boot carpet, Stain, Cleaning

50,00



Ceiling, Hole, Smart repair

64,32



Maintenance, Maintenance, Execute

0,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Sill outer R, Scratch(es), It - Spot repair

115,56



Door F L, Dent(s), Acceptable

0,00

No pictures to display