



<b>BMW X5: HA9209</b>			
Vinnumber:	<b>WBAKS410700H60175</b>	Versionname:	<b>X5 3.0dA xDrive30 258PK Aut.</b>
First Registrationdate:	<b>9/02/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>189058</b>	Power Kw:	<b>190</b>
Bodytype:		Body color:	<b>Dark Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2814</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	<b>HD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>255/50/19/107 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

<b>Assistance equipment</b>			
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>3774,98</b>
--------------------------	----------------

<b>Wing F R, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

<i>No pictures to display</i>	
-------------------------------	--

<b>Wing F L, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

<i>No pictures to display</i>	
-------------------------------	--

<b>Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>382,02</b>
--	---------------



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Rocker panel inner F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical polution, 67 - Polish 0,00

*No pictures to display*

Wing R L, Dent(s), LI - Repair and paint (complete) 369,84



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Tear, Smart repair 110,64



Door panel R R, Tear, Smart repair 110,64



Boot carpet, Damaged, E - Replace 20,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56



Door seal R L, Deformed / Strained, E - Replace 60,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Repaired, Acceptable


0,00



Door R L, Scratch(es), LI - Repair and paint (complete)

382,02





Seat cover F L, Worn, Acceptable

0,00



Rocker panel inner R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Tailgate, Scratch(es), LI - Repair and paint (complete)

362,02



Mirror side blinker R, Scratch(es), E - Replace

31,20



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00

