



BMW 3 GRAN TURISMO: 1L SH644

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber: | WBA8Y51020G430530 | Versionname: | 2.0 318D (100KW) GRAN TURISMO |
| First Registrationdate: | 23/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 183004 | Power Kw: | 100 |
| Bodytype: | | Body color: | Dark Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2116 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-------------------|
| Radio CD | Central consol F | |
| Windows electric F | Luggage cover | |
| Windows electric R | Rear parking sensors | |
| Cruise Control | Type of Tow bar | No Tow bar |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | No GPS | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 225/55/17/97 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|-------------------|---------|
| Total cost ex VAT | 1034,74 |
|-------------------|---------|

| | |
|-----------------------------------|------|
| Tailgate, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-------------------------------|------|
| Wing R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

No pictures to display

| | |
|--------------------------------|--------|
| Windscreen, Crack, E - Replace | 487,20 |
|--------------------------------|--------|



| | |
|---|--------|
| Wing F R, Scratch(es), LI - Repair and paint (complete) | 220,18 |
|---|--------|



| | |
|---|--------|
| Bumper F, Scratch(es), It - Spot repair | 115,56 |
|---|--------|



| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|------|
| Wing R R, Dent(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|------------------------------------|------|
| Alloy Rims (all), Rust, Acceptable | 0,00 |
|------------------------------------|------|

No pictures to display

| | |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|

