



**VOLVO V60: 1PLD795**

Vinnumber:	<b>YV1FW74C1G1326183</b>	Versionname:	<b>2.0 D2 VOLVO OCEAN RACE</b>
First Registrationdate:	<b>1/08/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>111946</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2612</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>










**Degree of wear**

	<b>235/40/18/92 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>2990,73</b>
<b>Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>			<b>0,00</b>



Ignition key, Missing, E - Replace		150,00
<i>No pictures to display</i>		
Windscreen, Stone chip(s), E - Replace		0,00
		
Rearview mirror L complete, Crack, E - Replace		168,00
		
Tyre R L, Tear, E - Replace		132,00
		
Alloy rim F L polished, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Chemical polution, LI - Repair and paint (complete)		290,08
		
Tyre F R, Tear, E - Replace		132,00
		
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Outer door handle R R, Scratch(es), LI - Repair and paint (complete)		0,00
		
Interior, Dirty, Cleaning		50,00
		
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)		366,35
		
Roof, Chemical polution, LI - Repair and paint (complete)		481,50





Outer door handle F R, Crack, Le - Replace and paint

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Dent(s), Acceptable

0,00

*No pictures to display*

Luggage space cover, Missing, E - Replace

240,00



Tyre R R, Tear, E - Replace

132,00



Rear window, Scratch(es), E - Replace

0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Dent(s), LI - Repair and paint (complete)

0,00



Alloy rim F R polished, Scratch(es), E - Replace

235,20



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Dent(s), Acceptable

0,00

*No pictures to display*