



AUDI A1: 1HCL452

Vinnumber:	WAUZZZ8X7EB119904	Versionname:	A1 SB Attraction 90PK
First Registrationdate:	18/06/2014	Fiscalpower:	
Expertise Mileage:	102569	Power Kw:	66
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2719
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Luggage cover	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/15/88 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3170,58
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

246,56



Rear spoiler, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display


Door F R, Scratch(es), LI - Repair and paint (complete)

254,68



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

176,14



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

176,14



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)


254,68





Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44



Rear window, Scratch(es), E - Replace

320,00




Wing R L, Scratch(es), LI - Repair and paint (complete)

246,56




Roof, Chemical polution, LI - Repair and paint (complete)

385,20



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

232,06



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), LI - Repair and paint (complete)	254,68

