



**AUDI A5 SPORTBACK: 1KCG288**

Vinnumber:	<b>WAUZZZ8T3FA052948</b>	Versionname:	<b>2.0 TDI ULTRA 100KW</b>
First Registrationdate:	<b>31/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>188517</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1523</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/50/17/94 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	<b>1773,72</b>
Door R L, Dent(s), PDR - Paintless dent repair	<b>63,00</b>



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical polution, 67 - Polish 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer R, Dent(s), LI - Repair and paint (complete) 372,60



Tailgate, Scratch(es), Acceptable 0,00

Language, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)		254,16
Rearview mirror housing L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)		369,84
Floor covering F L, Hole, Smart repair		64,32
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
Windscreen, Stone chip(s), Acceptable		0,00
Wing F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Covering interior A pillar L, Hole, Smart repair		110,64



Seat cover F L, Worn, Acceptable

0,00

