



MERCEDES A180: 1LKL925

Vinnumber:	WDD1760121V111166	Versionname:	1.5 A 180 CDI STYLE
First Registrationdate:	13/10/2015	Fiscalpower:	
Expertise Mileage:	84096	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	ASS A PLUS 312 D	Parking lot:	2214
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	No	Compressor	No
------------	-----------	------------	-----------


Total cost ex VAT	1111,56
Tyre repair kit, Missing, E - Replace	210,53



Bumper F L, Scratch(es), It - Spot repair 115,56





Tailgate, Repaired, Acceptable 0,00



Wing R R, Repaired, Acceptable 0,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 366,35



Compressor, Missing, E - Replace 0,00



Bumper R, Dent(s), LI - Repair and paint (complete) 259,80



Rear window, Scratch(es), E - Replace 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

53,00



Door R R, Repaired, Acceptable

0,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Seat cover F L, Scratch(es), Smart repair

64,32

