



VOLVO V40 CROSS COUNTRY: 1LEH296

Vinnumber:	YV1MZ74L1G2095597	Versionname:	2.0 D2 SUMMUM
First Registrationdate:	4/09/2015	Fiscalpower:	
Expertise Mileage:	57673	Power Kw:	88
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LKW2
Maintenance:	IN 28223 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 H LightMetal				
Winter tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 4 mm	Re.R.	Kleber: 4 mm

Assistance equipment

Repair kit	No	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1663,15

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Bumper Trim F, Scratch(es), Smart repair

110,64



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Door F L, Scratch(es), 67 - Polish

0,00

No pictures to display

Tyre repair kit, Missing, E - Replace

210,53



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Spoiler R, Scratch(es), It - Spot repair

115,56



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar R, Dent(s), Acceptable

0,00

No pictures to display

Bumper moulding R, Scratch(es), Le - Replace and paint

100,00



Wing F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Protection plate M, Hole, E - Replace	174,44
---------------------------------------	--------



Door R R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display