



MERCEDES E BREAK: 1XGB171

Vinnumber:	WDD2122981B083197	Versionname:	2.1 E 300 BLUETEC HYBRID AVANTGARDE AUTO
First Registrationdate:	25/11/2014	Fiscalpower:	
Expertise Mileage:	149326	Power Kw:	170
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2103
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/45/17/92 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	883,74
-------------------	---------------

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	-------------

No pictures to display

Rearlight L, Crack, E - Replace	132,00
---------------------------------	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Maintenance, Maintenance, Execute 0,00

No pictures to display

Door R R, Dent(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), It - Spot repair 115,56



Alloy rim F L polished, Rust, Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02

