


BMW 1 HATCH: 1NFZ273

Vinnumber:	WBA1V91040V736092	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	16/02/2016	Fiscalpower:	
Expertise Mileage:	91545	Power Kw:	85
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	SHOWROOM
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/92 MS LightMetal			
Winter tyres:	Fr.L.	Fr.R.	Michelin: 4 mm
	Re.L.	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1291,50
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35



Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s), PDR - Paintless dent repair	63,00
 	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
 	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
 	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
  	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
 	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
 	
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
  	