



RENAULT Clio: 1GVQ872

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | VF17RFL0H50807022 | Versionname: | CLIO IV BRE Energy Dynamique 90PK |
| First Registrationdate: | 13/05/2014 | Fiscalpower: | |
| Expertise Mileage: | 69753 | Power Kw: | 66 |
| Bodytype: | | Body color: | Red |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | PARKING GARAGE |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Windows electric F | Central consol F |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 195/55/16/92 H LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|--|---------------|
| Total cost ex VAT | 543,68 |
| Bumper corner R L, Scratch(es), It - Spot repair | 115,56 |



Protection plate M, Deformed / Strained, E - Replace

62,00



Boot cover, Missing, E - Replace

40,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Tailgate, Scratch(es), It - Spot repair

115,56



Bumper R, Scratch(es), It - Spot repair

115,56

