


**MERCEDES A: 1LBU572**

Vinnumber:	<b>WDD1760121V090925</b>	Versionname:	<b>1.5 A 180 CDI</b>
First Registrationdate:	<b>13/08/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>93974</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2514</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/91 V Steel</b>				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1992,03</b>
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>211,80</b>



Rocker panel inner F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 356,20



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Rearview mirror L complete, Scratch(es), Acceptable 0,00



Wheel cover R L, Scratch(es), E - Replace 30,00



Wheel cover F L, Missing, E - Replace 30,00



Rear window, Scratch(es), E - Replace 370,00





Rocker panel inner R L, Dent(s), Acceptable 0,00

*No pictures to display*

Seat cover F L, Worn, Acceptable 0,00



Seat cover F L, Stain, Cleaning 25,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Steel rim F L, Deformed / Strained, E - Replace 88,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover F R, Missing, E - Replace 30,00



Door F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Rearview mirror R complete, Scratch(es), Acceptable 0,00



Wheel cover R R, Scratch(es), E - Replace 30,00



GPS, Not functioning (well), Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00

*No pictures to display*