



PEUGEOT 508 SW: 1LHC918

Vinnumber:	VF38UAHWTFLO27765	Versionname:	2.0 BLUEHDI 133KW AUTO S/S 2WD RXH
First Registrationdate:	28/09/2015	Fiscalpower:	
Expertise Mileage:	101060	Power Kwr:	133
Bodytype:		Body color:	Anthracite
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	DEPASSE DE 7.800 KM	Parking lot:	3101
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	245/45/18/100 V LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1283,51
-------------------	----------------

Bumper moulding F M, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Bumper moulding F L, Scratch(es), Le - Replace and paint

100,00



Rearview mirror basis R, Scratch(es), Smart repair

110,64



Bumper moulding R, Scratch(es), Smart repair

110,64



Door F R, Dent(s), LI - Repair and paint (complete)

0,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

307,80





Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F L, Scratch(es), It - Spot repair

115,56



Mirror side blinker L, Broken, E - Replace

30,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Front compartment engine mounting, Tear, E - Replace

128,87



Maintenance, Maintenance, Execute

0,00



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display