



BMW 518: 1LBE688

Vinnumber:	WBA5E31060G040546	Versionname:	518
First Registrationdate:	7/08/2015	Fiscalpower:	
Expertise Mileage:	142962	Power Kw:	100
Bodytype:		Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2811
Maintenance:	PLUS 16000 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1715,38
-------------------	----------------

Wing R R, Dent(s) and scratch(es), Acceptable	0,00
---	-------------



Door F R, Repaired, Acceptable	0,00
--------------------------------	-------------



Bonnet, Dent(s), Acceptable 0,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Door R R, Bad repair, Acceptable 0,00



Wing F R, Dent(s) and scratch(es), Acceptable 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Dent(s) and scratch(es), Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Rearview mirror basis R, Scratch(es), Acceptable 0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 417,84



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Dent(s), Acceptable 0,00



Roof, Dent(s), PDR - Paintless dent repair 142,20

