



BMW 2 Active Tourer: 1JLG446

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------------|
| Vinnumber: | WBA2C11090VZ55836 | Versionname: | 2 ACTIVE TOURER 218d 136PK |
| First Registrationdate: | 16/01/2015 | Fiscalpower: | |
| Expertise Mileage: | 104570 | Power Kw: | 100 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | - | Parking lot: | 2816 |
| Maintenance: | NOT OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|--------------------------|
| Windows electric F | Central consol F | |
| Windows electric R | Luggage cover | |
| Cruise Control | Rear parking sensors | |
| Steering wheel multifunctional | Type of Tow bar | Tow bar removable |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|----------------|-------|----------------|
| 205/60/16/92 H LightMetal | | | | |
| Winter tyres: | Fr.L. | Goodyear: 5 mm | Fr.R. | Goodyear: 5 mm |
| | Re.L. | Goodyear: 5 mm | Re.R. | Goodyear: 5 mm |

Assistance equipment

| | | | |
|---|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 805,00 |
| Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) | | | 308,20 |



Wing R R, Dent(s), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Maintenance, Maintenance, Execute

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

