



Ford Transit: 1DLF436			
Vinnumber:	WF05XXBDF5CA33949	Versionname:	
First Registrationdate:	14/06/2012	Fiscalpower:	
Expertise Mileage:	91921	Power Kw:	74
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV13
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/70/15/104 T Steel			
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2680,69
Bumper R, Missing, E - Replace			329,40



Wheel cover F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)		303,15



Bodywork, Accident, Repair/replace (lump sum) 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Rust, Acceptable 0,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 328,88



Floor covering F L, Tear, E - Replace 237,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Door frame F L, Rust, LI - Repair and paint (complete) 150,00



Trunk door R L, Dent(s), Le - Replace and paint 862,35



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76

