



VOLVO V40: 1LVE154

Vinnumber:	VV1MV2181G2320434	Versionname:	2.0 T2 ECO MOMENTUM
First Registrationdate:	15/12/2015	Fiscalpower:	
Expertise Mileage:	79944	Power Kw:	90
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4210
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2465,67
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18




Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Rear spoiler, Chemical polution, LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door R R, Scratch(es), Acceptable

0,00

No pictures to display


Door R L, Scratch(es), LI - Repair and paint (complete)

318,35




Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display