



BMW 2 GRAN TOURER: 1LUH654

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber: | WBA2E31040P791678 | Versionname: | 1.5 216D GRAN TOURER |
| First Registrationdate: | 8/12/2015 | Fiscalpower: | |
| Expertise Mileage: | 170926 | Power Kw: | 85 |
| Bodytype: | | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metallic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 1725 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 7 | | |
| Number head rests: | 7 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|----------------------------------|
| Windows electric F | Central consol F |
| Cruise Control | Luggage cover |
| Steering wheel multifunctional | Front parking sensors |
| Radio multimedia | Rear parking sensors |
| Type of headlighting | Type of Tow bar |
| Type of GPS | Headlighting LED |
| Type of Lining | GPS big screen color |
| Type of climate control | Lining artificial leather |
| | Autom climate control |
| | Tow bar removable |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
| Winter tyres: | 205/55/17/92 MS LightMetal | | | |
| | Fr.L. | Continental: 3 mm | Fr.R. | Continental: 3 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |
| | | | | |

Assistance equipment

| | |
|---|--------|
| Total cost ex VAT | 991,00 |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 259,80



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Foglight L, Deformed / Strained, E - Replace 138,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Tailgate, Dent(s), Le - Replace and paint 0,00

