



**BMW 2 ACTIVE TOURER: 1LRA931**

Vinnumber:	<b>WBA2B31040V691777</b>	Versionname:	<b>1.5 216D ACTIVE TOURER</b>
First Registrationdate:	<b>10/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>146197</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2404</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/96 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 2550,54

Door F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Windscreen, Stone chip(s), Windscreen repair

58,80



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Ignition key, Missing, E - Replace

150,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Outer door handle F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Rearview mirror L complete, Crack, E - Replace

168,00



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Tailgate, Dent(s), LI - Repair and paint (complete)

349,68



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Certificate Of Conformity, Missing, E - Replace	150,00
---	--------



Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Roof pillar L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

