



**BMW X2: 1UQX588**

|                                    |                          |              |                        |
|------------------------------------|--------------------------|--------------|------------------------|
| Vinnumber:                         | <b>WBAYH11050EM63865</b> | Versionname: | <b>sDrive18i 100kW</b> |
| First Registrationdate:            | <b>12/07/2018</b>        | Fiscalpower: |                        |
| Expertise Mileage:                 | <b>25456</b>             | Power Kw:    | <b>100</b>             |
| Bodytype:                          |                          | Body color:  | <b>Gold</b>            |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>         |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>       |
| Fueltype:                          | <b>Petrol</b>            | Oil level:   | <b>OK</b>              |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>3114</b>            |
| Battery functioning:               | <b>Yes</b>               |              |                        |
| Number of doors:                   | <b>5</b>                 |              |                        |
| Number of seats:                   | <b>5</b>                 |              |                        |
| Number head rests:                 | <b>5</b>                 |              |                        |
| Rims summer:                       | <b>Aluminium</b>         |              |                        |
| Category:                          | <b>Passenger Car</b>     |              |                        |
| Oil level:                         | <b>OK</b>                |              |                        |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                        |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Windows electric F             | Central consol F                 |
| Windows electric R             | Luggage cover                    |
| Cruise Control                 | Front parking sensors            |
| Steering wheel multifunctional | Rear parking sensors             |
| Radio multimedia               |                                  |
| Type of headlighting           | <b>Headlighting Halogen</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>225/55/17/92 H LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Goodyear: 4 mm</b> | Fr.R. | <b>Goodyear: 4 mm</b> |
|                                  | Re.L. | <b>Goodyear: 5 mm</b> | Re.R. | <b>Goodyear: 5 mm</b> |

**Assistance equipment**

|   |        |
|---|--------|
| Total cost ex VAT                       | 225,56 |
| Bumper F, Scratch(es), It - Spot repair | 115,56 |



Model badge R, Not original part, Acceptable 0,00



|  |       |
|--|-------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|                                   |      |
|-----------------------------------|------|
| Tailgate, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|                                      |       |
|--------------------------------------|-------|
| Bodywork, Not original part, Forfeit | 15,00 |
|--------------------------------------|-------|

*No pictures to display*