



VOLVO V60 CROSS COUNTRY: 1LSN383

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber: | VV1FZARCDG1012691 | Versionname: | 2.0 D3 GEARTRONIC SUMMUM |
| First Registrationdate: | 24/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 195842 | Power Kw: | 110 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2104 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD | | Seats electric F L | |
| Windows electric F | | Central consol F | |
| Windows electric R | | Luggage cover | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | Tow bar removable |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-------------------------|-------|-------------------------|
| | 235/50/18/101 V LightMetal | | | |
| Winter tyres: | Fr.L. | Vredestein: 2 mm | Fr.R. | Vredestein: 2 mm |
| | Re.L. | Vredestein: 4 mm | Re.R. | Vredestein: 4 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|-------------------|--------|
| Total cost ex VAT | 306,80 |
|-------------------|--------|

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|------|
| Door panel F R, Scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|---|-------|
| Door panel R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R L polished, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wheel arch cover F L, Deformed / Strained, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F L polished, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |

