


**RENAULT ESPACE: 1LUU864**

Vinnumber:	<b>VF1RFC00354117271</b>	Versionname:	<b>1.6 DCI 160 EDC ENERGY INTENS</b>
First Registrationdate:	<b>10/12/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>130100</b>	Power Kw:	<b>118</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>NOT OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>PARKING VOORAAN</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Sun Roof electric
GPS storage	<b>HD</b>	Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Radio multimedia		
Type of headlighting	<b>Headlighting LED</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>NOT OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>No</b>
Idle position	<b>NOT OK</b>	Sound engine	<b>NOT OK</b>
Engine startingtime	<b>NOT OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>NOT OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>NOT OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/55/19/105 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Dunlop: 4 mm</b>	Fr.R.	<b>Dunlop: 4 mm</b>
	Re.L.	<b>Continental: 3 mm</b>	Re.R.	<b>Continental: 3 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1684,96</b>
Ignition key, Missing, E - Replace	<b>150,00</b>



Rearview mirror L complete, Broken, E - Replace

192,00



Bumper corner R R, Scratch(es), It - Spot repair

115,56



Door F L, Dent(s), Acceptable

0,00

*No pictures to display*

Door R L, Dent(s), Acceptable

0,00

*No pictures to display*

Rearview mirror housing R, Scratch(es), Acceptable

0,00

*No pictures to display*

Tailgate, Scratch(es), LI - Repair and paint (complete)

362,02



Trunk lid covering R, Scratch(es), Smart repair

110,64



Alloy rim R R polished, Scratch(es), Acceptable

0,00

*No pictures to display*

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Engine, Not functioning (well), Acceptable

0,00



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56

