


PEUGEOT 508 SW: 1KPC864

Vinnumber:	VF38EAHSMFL022848	Versionname:	2.0 BLUEHDI 100KW S/S ACTIVE
First Registrationdate:	8/06/2015	Fiscalpower:	
Expertise Mileage:	131027	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3708
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Rear parking sensors	
Radio multimedia	Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/17/98 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3158,54
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00




Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Door F L, Dent(s), LI - Repair and paint (complete)

318,35




Rear spoiler, Chemical pollution, LI - Repair and paint (complete)

115,56




Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

462,35



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete)

481,50



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 452,20



Rear window, Scratch(es), E - Replace 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display