



VOLKSWAGEN GOLF: 1HCZ524

Vinnnummer:	WVWZZZAUZEW340716	Versionname:	
First Registrationdate:	20/06/2014	Fiscalpower:	77
Expertise Mileage:	138297	Power Kw:	
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2103
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3307,65
Floor covering F L, Hole, Smart repair	64,32



Trunk lid covering R, Scratch(es), Smart repair

110,64



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

481,50



Bumper R, Hole, Le - Replace and paint

651,00



Rear wiper arm, Missing, E - Replace

25,00



Ignition key, Missing, E - Replace

150,00



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Rearview mirror L complete, Broken, Le - Replace and paint

283,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Internal Boot Lining L, Broken, Smart repair 110,64



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Stone chip(s), Windscreen repair 58,80

