



| | | | |
|------------------------------------|--------------------------|--------------|-------------------------|
| BMW 3: 1GWL891 | | | |
| Vinnnumber: | WBA3D91000F406875 | Versionname: | 3 BER 316d 116PK |
| First Registrationdate: | 20/05/2014 | Fiscalpower: | |
| Expertise Mileage: | 126863 | Power Kw: | 85 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | PARKING VOORAAN |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| | |
|--------------------------------|----------------------------------|
| Options | |
| Radio CD | Central consol F |
| GPS storage | Rear parking sensors |
| GPS storage | HD |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

| | | | |
|-------------------------------------|-----------|---------------------|---------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | NOT OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | NOT OK |
| | | Lighting | NOT OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| Degree of wear | | | | |
| | 205/60/16/92 H LightMetal | | | |
| Winter tyres: | Fr.L. | Bridgestone: 3 mm | Fr.R. | Bridgestone: 3 mm |
| | Re.L. | Bridgestone: 3 mm | Re.R. | Bridgestone: 3 mm |

| | | | |
|--|------------|------------|------------|
| Assistance equipment | | | |
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--|----------------|
| Total cost ex VAT | 1248,88 |
| Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Grill frame, Broken, E - Replace 164,20



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display


Tailgate, Dent(s), PDR - Paintless dent repair 63,00



Ignition key, Missing, E - Replace 150,00



Roof, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

