



**HYUNDAI TUCSON: 1NPE769**

Vinnumber:	<b>TMAJ381AAGJ138256</b>	Versionname:	<b>2.0 CRDI 100KW ISG PREMIUM</b>
First Registrationdate:	<b>31/03/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>183314</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3510</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/60/17/103 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Compressor	<b>Yes</b>
Repair kit	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>2205,47</b>
<b>Bumper R, Scratch(es), It - Spot repair</b>	<b>115,56</b>



Trunk lid covering R, Scratch(es), Smart repair 110,64



Door R L, Scratch(es), E - Replace 94,60



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 362,02



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 348,09



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Door seal F L, Deformed / Strained, E - Replace 60,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper corner R L, Scratch(es), It - Spot repair 115,56





Bumper moulding R L, Scratch(es), Smart repair 110,64



Door panel R L, Scratch(es), E - Replace 132,00



Roof, Chemical polution, LI - Repair and paint (complete) 577,80



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display