



**VOLVO XC90: 1LSF103**

Vinnumber:	<b>YV1LFA88DG1046352</b>	Versionname:	<b>2.0 D4 FWD GEARTRONIC MOMENTUM 7PL.</b>
First Registrationdate:	<b>20/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>201797</b>	Power Kw:	<b>140</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Wheel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1308</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Sun Roof electric
GPS storage		Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/55/19/105 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	<b>1088,30</b>
Roof, Chemical polution, LI - Repair and paint (complete)	<b>0,00</b>



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Wing F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bonnet, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing trim R R, Scratch(es), Acceptable

0,00



Bumper corner R L, Scratch(es), It - Spot repair

115,56



Door moulding Lower R R, Scratch(es), Smart repair

0,00



Door F L, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), It - Spot repair

115,56



Door F R, Dent(s), PDR - Paintless dent repair

63,00

