



VOLKSWAGEN TOURAN: 1LSN517

| | | | |
|------------------------------------|-------------------|--------------|--------------------------------|
| Vinnnumber: | WVGZZZ1TZGW514960 | Versionname: | 1.6 TDI SCR 81KW BMT TRENDLINE |
| First Registrationdate: | 24/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 137941 | Power Kw: | 81 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metallic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2712 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|-----------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | SD | Luggage cover |
| GPS storage | | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Seats F heated | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|----|---------------------|-----|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------|----------------|-------|----------------|
| | 205/60/16/92 MS Steel | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|------------|-----|------------|-----|
| Repair kit | Yes | Compressor | Yes |
|------------|-----|------------|-----|

Total cost ex VAT 952,60

Storage compartment housing, Broken, E - Replace 52,00



Seat cover F L, Stain, Cleaning 0,00



Door F R, Dent(s), PDR - Paintless dent repair 63,00

No pictures to display

Reflector, Broken, E - Replace 24,60



Wing R R, Bad repair, LI - Repair and paint (complete) 0,00



Seat cover F R, Stain, Cleaning 0,00

No pictures to display

Bumper F, Scratch(es), 67 - Polish 0,00

No pictures to display

Rearlight L, Broken, E - Replace 114,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Stone chip(s), E - Replace 487,20

