



VOLKSWAGEN Polo: PA9096

Vinnumber:	WVWZZZ6RZFY151967	Versionname:	POLO BER Trendline BMT 90PK
First Registrationdate:	30/10/2014	Fiscalpower:	
Expertise Mileage:	111057	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3710
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Windows electric R	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/70/14/84 MS Steel			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2041,46
-------------------	---------

Wing F R, Scratch(es), LI - Repair and paint (complete)	176,14
---	--------



Roof, Dent(s), Acceptable	0,00
---------------------------	------

No pictures to display

Bumper R, Crack, I.e - Replace and paint	535,20
--	--------

Bumper R, Scratch(es), E - Replace and paint

320,00



Rear window, Scratch(es), E - Replace

413,76



Windscreen, Scratch(es), E - Replace

254,68



Door R L, Dent(s), LI - Repair and paint (complete)

254,68



Door F R, Scratch(es), LI - Repair and paint (complete)

63,00



Roof, Dent(s), PDR - Paintless dent repair

24,00



Wheel cover F R, Missing, E - Replace

