



SKODA Superb: 1JFU765

Vinnumber:	TMBAJ73T1F9031486	Versionname:	SUPERB BER GreenLine Ambition 105PK
First Registrationdate:	5/12/2014	Fiscalpower:	
Expertise Mileage:	123389	Power Kw:	77
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1433
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/92 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT

1961,22

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00




Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Bad repair, LI - Repair and paint (complete)

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Bad repair, LI - Repair and paint (complete)

0,00



Bumper F M, Dent(s) and scratch(es), Smart repair

110,64



Windscreen, Scratch(es), E - Replace

487,20



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Rearlight R , Scratch(es), 67 - Polish	0,00
--	------

No pictures to display