



HONDA JAZZ: 1CNZ924			
Vinnumber:	LUCGG275093214174	Versionname:	
First Registrationdate:	4/11/2009	Fiscalpower:	
Expertise Mileage:	276507	Power Kw:	66
Bodytype:		Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3614
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	175/65/15/84 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2812,16
Bonnet, Chemical polution, 67 - Polish	0,00





Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair 82,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s), LI - Repair and paint (complete) 302,68



Ignition key, Missing, E - Replace 150,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s), LI - Repair and paint (complete) 302,68



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 246,56



Alloy rim R R, Scratch(es), Acceptable 0,00

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical pollution, LI - Repair and paint (complete) 529,20



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 342,56



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Tailgate, Dent(s), PDR - Paintless dent repair 63,00

