



BMW X5: 1EGN779

Vinnumber:	WBAKT010000U32390	Versionname:	
First Registrationdate:	26/10/2016	Fiscalpower:	
Expertise Mileage:	136438	Power Kw:	180
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2506
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

275/40/20/106 W LightMetal				
Summer tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 3 mm	Re.R.	Dunlop: 3 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2305,70
--------------------------	----------------

Alloy rim R L, Scratch(es), Acceptable	0,00
-----------------------------------------------	-------------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
----------------------------------------------------------------	---------------




Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete)

348,09




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Dent(s), LI - Repair and paint (complete)

254,16



Charging cable (normal), Missing, E - Replace

380,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Wing trim R R, Scratch(es), It - Spot repair

115,25



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

