



VOLKSWAGEN TOURAN: 1NAE352

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------------|
| Vinnumber: | WVGZZZ1TZGW518604 | Versionname: | 1.6 TDI SCR 81KW BMT TRENDLINE |
| First Registrationdate: | 4/01/2016 | Fiscalpower: | |
| Expertise Mileage: | 113380 | Power Kw: | 81 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 1310 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--|
| Radio CD | | Central consol F | |
| GPS storage | SD | Luggage cover | |
| GPS storage | | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-------------------------|-------|-------------------------|
| | 205/60/16/92 MS LightMetal | | | |
| Winter tyres: | Fr.L. | Vredestein: 4 mm | Fr.R. | Vredestein: 4 mm |
| | Re.L. | Vredestein: 5 mm | Re.R. | Vredestein: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 211,80 |
|-------------------|---------------|

| | |
|--|-------------|
| Bumper F, Bad repair, LI - Repair and paint (complete) | 0,00 |
|--|-------------|




| | |
|--|------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|-----------------------------|------|
| Bonnet, Dent(s), Acceptable | 0,00 |
|-----------------------------|------|

No pictures to display

| | |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|--|------|
| Wing F L, Bad repair, LI - Repair and paint (complete) | 0,00 |
|--|------|



| | |
|------------------------------------|------|
| Roof pillar L, Dent(s), Acceptable | 0,00 |
|------------------------------------|------|

No pictures to display