



VOLVO XC60: 1HAV977

Vinnumber:	YV1DZ31A1F2631878	Versionname:	XC60 D3 Kinetic 136PK
First Registrationdate:	5/06/2014	Fiscalpower:	
Expertise Mileage:	188420	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4703
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/104 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1485,36
-------------------	----------------

Door R L, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair	63,00
--	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Scratch(es), Forfeit 105,00



Dashboard, Scratch(es), Acceptable 0,00



Backrest cover F R, Scratch(es), Acceptable 0,00



Roof pillar L, Dent(s), Acceptable 0,00


No pictures to display

Bumper spoiler F, Scratch(es), It - Spot repair 115,56



Roof, Scratch(es), LI - Repair and paint (complete) 577,80





Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84

