



MERCEDES SPRINTER: 1NGZ295

Vinnumber:	WDB9066331P238416	Versionname:	1.8 16V CNG 316 NGT BI-FUEL A2H1 3.5T
First Registrationdate:	23/02/2016	Fiscalpower:	
Expertise Mileage:	58143	Power Kw:	115
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance	- 425 DAGEN	Parking lot:	LCV30
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/16/115 R Steel				
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	No	Jack	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3107,42
Sliding door R, Dent(s), LI - Repair and paint (complete)	382,02



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 327,15



Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display

Spare wheel, Missing, E - Replace 153,60

No pictures to display

Bodywork, Dirty, P - Check 0,00



Jack, Missing, E - Replace 42,00

No pictures to display

Internal Boot Lining R, Broken, E - Replace 35,00



Maintenance, Maintenance, Execute 0,00



Sidewall mid L (LCV) , Dent(s) and scratch(es), LI - Repair and paint (complete) 478,02



Parking sensor R, Not functioning (well), E - Replace 140,35



Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete) 526,02



Bumper corner R R, Deformed / Strained, E - Replace 77,07



Wheel aperture R L, Dent(s), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Deformed / Strained, E - Replace 329,40



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 280,88



Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Reflector, Broken, E - Replace 8,76



Wing R L, Dent(s), LI - Repair and paint (complete) 327,15

