



SKODA OCTAVIA COMBI: 1JSP584

Vinnumber:	TMBJG7NE7F0173326	Versionname:	1.6 CRTDI 77KW GREENTEC AMBITION
First Registrationdate:	16/02/2015	Fiscalpower:	
Expertise Mileage:	98634	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2815
Maintenance:	OVER 10200 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1121,26
Door R R, Scratch(es), 67 - Polish	50,00



Rearview mirror housing L, Broken, E - Replace

64,31



Wheel cover R R, Scratch(es), E - Replace

30,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Door R L, Repaired, P - Check

0,00



Bodywork, Not original part, Remove lettering

25,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper trim R, Scratch(es), E - Replace

168,00



Protection plate M, Hole, E - Replace

32,83

