



**AUDI A3 SPORTBACK: 1JUS352**

|                                    |                          |              |                                |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber:                         | <b>WAUZZZ8V8FA128116</b> | Versionname: | <b>1.6 TDI 81KW ATTRACTION</b> |
| First Registrationdate:            | <b>2/03/2015</b>         | Fiscalpower: |                                |
| Expertise Mileage:                 | <b>148108</b>            | Power Kw:    | <b>81</b>                      |
| Bodytype:                          |                          | Body color:  | <b>Blue</b>                    |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                 |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>               |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2410</b>                    |
| Number of doors:                   | <b>5</b>                 |              |                                |
| Number of seats:                   | <b>5</b>                 |              |                                |
| Number head rests:                 | <b>5</b>                 |              |                                |
| Rims summer:                       | <b>Aluminium</b>         |              |                                |
| Category:                          | <b>Passenger Car</b>     |              |                                |
| Oil level:                         | <b>OK</b>                |              |                                |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                |

**Options**

|                                |                              |                      |                   |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD                       |                              | Central consol F     |                   |
| GPS storage                    | <b>SD</b>                    | Luggage cover        |                   |
| GPS storage                    |                              | Rear parking sensors |                   |
| Windows electric F             |                              | Type of Tow bar      | <b>No Tow bar</b> |
| Windows electric R             |                              |                      |                   |
| Steering wheel multifunctional |                              |                      |                   |
| Radio multimedia               |                              |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                   |
| Type of climate control        | <b>Autom climate control</b> |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                         |       |                         |
|---------------|----------------------------------|-------------------------|-------|-------------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                         |       |                         |
| Winter tyres: | Fr.L.                            | <b>Vredestein: 7 mm</b> | Fr.R. | <b>Vredestein: 7 mm</b> |
|               | Re.L.                            | <b>Michelin: 5 mm</b>   | Re.R. | <b>Michelin: 5 mm</b>   |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>325,00</b> |
|-------------------|---------------|

|   |             |
|---|-------------|
| Outside rear-view mirror housing R, Scratch(es), Acceptable | <b>0,00</b> |
|---|-------------|

*No pictures to display*

|   |             |
|---|-------------|
| Inner door sill RR, Scratch(es), Acceptable | <b>0,00</b> |
|---|-------------|

*No pictures to display*

|                              |             |
|------------------------------|-------------|
| Wing RR, Dent(s), Acceptable | <b>0,00</b> |
|------------------------------|-------------|

*No pictures to display*

|                          |              |
|--------------------------|--------------|
| Interior Stain, Cleaning | <b>40,00</b> |
|--------------------------|--------------|



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, Acceptable 0,00

No pictures to display

Alloy rim RR, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical polution, Acceptable 0,00

No pictures to display

Alloy rim FL, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Broken, E - Replace 0,00



Inner door sill RL, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim FR, Scratch(es), LI - Repair and paint (complete) 95,00

