


BMW 1 HATCH: 1PVG719

Vinnumber:	WBA1V910605D74320	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	28/09/2016	Fiscalpower:	
Expertise Mileage:	142367	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3118
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 WINTER H LightMetal			
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1827,34
Wing RR, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim FL, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door RR, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Roof, Dent(s), Acceptable			0,00


Rooftop, Dent(s), Acceptable 0,00

No pictures to display

Wing RL, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wheel arch cover FL, Broken, E - Replace 63,06



Outer sill L, Scratch(es), Acceptable 0,00

No pictures to display

Grille, Broken, E - Replace 120,25



Seat cover FL, Worn, Acceptable 0,00



Wing FL, Scratch(es), Acceptable 0,00

No pictures to display

Door panel FL, Worn, Acceptable 0,00



Centre console, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim FR, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Dent(s) and scratch(es), Le - Replace and paint 735,00





Inner seat cover L, Broken, E - Replace	81,83
---	-------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Door FL, Dent(s) and scratch(es), Acceptable	0,00
--	------

No pictures to display

Windscreen, Stone chip(s), E - Replace	487,20
--	--------



Inner door sill FR, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------

No pictures to display

Alloy rim RR, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim RL, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Steering wheel, Worn, Acceptable	0,00
----------------------------------	------



Door FL, Dent(s), Acceptable	0,00
------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door FR, Dent(s), Acceptable	0,00
------------------------------	------

No pictures to display

Door panel RR, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Owner's manual, Missing, P - Check	0,00
------------------------------------	------

No pictures to display