



VOLKSWAGEN Polo: 1CER894

Vinnumber:	WVWZZZ6RZCY085630	Versionname:	POLO BER Trendline DPF 90PK
First Registrationdate:	7/11/2011	Fiscalpower:	
Expertise Mileage:	121934	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2609
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	185/60/15/92 MS Steel			
	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	821,12
-------------------	--------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rear window, Scratch(es), E - Replace	320,00
---------------------------------------	--------



Wheel cover FL, Scratch(es), E - Replace 24,00



Door FR, Scratch(es), Acceptable 0,00

No pictures to display

Door RR, Scratch(es), Acceptable 0,00

No pictures to display

Rear wiper arm, Incomplete, E - Replace 5,00



Wheel cover RL, Scratch(es), E - Replace 24,00



Wheel cover FR, Scratch(es), E - Replace 24,00



Door FL, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44

