



BMW 2 GRAN TOURER: 1LUB660

Vinnumber:	WBA2E510505C92754	Versionname:	2.0 218D (100KW) GRAN TOURER
First Registrationdate:	4/12/2015	Fiscalpower:	
Expertise Mileage:	100225	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3210
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2376,30
Wiper arm R, Not original part, P - Check	0,00



Alloy rim FL, Scratch(es), LI - Repair and paint (complete)

95,00



Door RR, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Inner door sill RR, Dent(s), LI - Repair and paint (complete)

115,56



Inner door sill RL, Dent(s), LI - Repair and paint (complete)

115,56



Wing RL, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door frame RR, Dent(s), It - Spot repair

115,56



Outside rear-view mirror base R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim RR, Scratch(es), LI - Repair and paint (complete)

95,00



Door RL, Scratch(es), LI - Repair and paint (complete)

318,35



Interior, Dirty, Cleaning

50,00



Door FR, Scratch(es), Acceptable

0,00

No pictures to display

Outer sill L, Scratch(es), It - Spot repair

115,56



Wing RR, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Door panel RL, Scratch(es), Acceptable

0,00



Alloy rim RL, Scratch(es), LI - Repair and paint (complete)

95,00



Wing FL, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim FR, Scratch(es), LI - Repair and paint (complete)

95,00



Door frame RL, Dent(s), It - Spot repair

115,56



Door FL, Scratch(es), Acceptable

0,00

No pictures to display

Door panel RR, Scratch(es), Acceptable

0,00

No pictures to display