



**TOYOTA AURIS TOURING SPORTS: 1RBT489**

Vinnumber:	<b>SB1Z53JE80E289231</b>	Versionname:	<b>1.8 HYBRID BUSINESS CVT AUTO</b>
First Registrationdate:	<b>8/11/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>143640</b>	Power Kw:	<b>73</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Rims summer:	<b>Aluminium</b>
Transmission:	<b>Front</b>	Oil level:	<b>OK</b>
Fueltype:	<b>Hybrid Petrol</b>	Parking lot:	<b>3533</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>194,60</b>
<b>Windscreen, Stone chip(s), Windscreen repair</b>	<b>0,00</b>



Door RR, Dent(s), Acceptable 0,00

No pictures to display

Bodywork, Not original part, P - Check 0,00



Wing FR, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Roof rail L, Bad repair, Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door FL, Scratch(es), Acceptable 0,00

No pictures to display

Wing RR, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Internal boot lining L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 0,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Door RL, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side repeater R, Broken, E - Replace 56,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door FR, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Dent(s), PDR - Paintless dent repair 69,30



Alloy rim FR, Scratch(es), LI - Repair and paint (complete) 0,00



Wing RL, Dent(s), PDR - Paintless dent repair 69,30

