



RENAULT Captur: 1HRF662

Vinnumber:	VF12RFL1H51497941	Versionname:	CAPTUR Energy Business 90PK
First Registrationdate:	11/09/2014	Fiscalpower:	
Expertise Mileage:	210375	Power Kw:	66
Bodytype:		Body colour:	Silver
Gearbox:	MAN 5 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1121
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

205/60/16/92 H				
Summer tyres:	Fr.L.	Goodyear: 4,7 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4,8 mm	Re.R.	Goodyear: 4,6 mm
Tyre profile depth FL:				4.7
Tyre profile depth FR:				3.0
Tyre profile depth RL:				4.8
Tyre profile depth RR:				4.6
Tyre size FL:				205/60 R 16 92 H
Tyre type FL:				All season
Tyre make FL:				259
Tyre make RL:				259

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	1327,41
Alloy rim RR, Scratch(es), Repair and paint (complete)	125,40



Alloy rim FL, Scratch(es), Repair and paint (complete)	125,40
---	---------------



Tailgate handle, Broken, Replace and paint

63,41



Door RL, Dent(s), Acceptable

0,00



Outside rear-view mirror housing L, Scratch(es), Paint

0,00



Outside rear-view mirror glass L, Broken, Replace

19,00



Door RR, Scratch(es), Acceptable

0,00



Seat cover FR, Burned, Smart repair

110,00



Wing RR, Dent(s), Acceptable

0,00



Windscreen, Scratch(es), Polish

0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

125,40



Step L, Dent(s) and scratch(es), Acceptable

0,00



Seat cover FL, Burned, Smart repair

110,00



Wing FR, Scratch(es), Acceptable

0,00



Tailgate / Boot, Bad repair, Check

0,00



Bumper R, Scratch(es), Acceptable

0,00



Wing trim FL, Scratch(es), Smart repair

110,00



Bumper spoiler F, Dent(s), Acceptable

0,00



Roof pillar L, Dent(s), Repair and paint (complete)

232,49



Door panel RR, Scratch(es), Acceptable

0,00



Wing FL, Scratch(es), Acceptable

0,00



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)

306,31



Bumper F, Scratch(es), Paint

0,00



Door FL, Dent(s), Acceptable

0,00

