Print

macadam vab inspection



TOYOTA PRIUS: 1YMZ370

Vinnumber:	**JTDKB3FU403094395**	Versionname:	**1.8 VVT-i Hybrid Lounge**
First Registrationdate:	**23/10/2020**	Fiscalpower:	
Expertise Mileage:	**27904**	Power Kw:	**90**
Bodytype:		Body colour	**Blue**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:		Parking lot	**3632**
Fueltype:	**Hybrid Petrol**		
Maintenance	**OK**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
Cruise Control		Type of Tow bar	**No Tow bar**
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	**Headlighting LED**		
Type of GPS	**GPS big screen color**		
Type of Lining	**Lining fabrics**		
Type of climate control	**Autom climate control**		

Limited Technical Inspection

Degree of wear

	215/45/17/92 H			
Summer tyres:	Fr.L.	**Yokohama: 5 mm**	Fr.R.	**Yokohama: 5 mm**
	Re.L.	**Yokohama: 5 mm**	Re.R.	**Yokohama: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**215/45 R 17 92 H**
Tyre type FL	**Summer**
Tyre make FL	**2481**
Tyre make RL	**2481**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**0**		
Number of charging cables (rapid charge)	**0**		

Total cost ex VAT	**831,86**
Alloy rim RR, Scratch(es), Repair and paint (complete)	**114,00**

Bumper F, Scratch(es), Acceptable	**0,00**

Alloy rim FL, Scratch(es), Repair and paint (complete)	114,00

Alloy rim RL, Scratch(es), Repair and paint (complete)	114,00

Alloy rim FR, Scratch(es), Repair and paint (complete)	114,00

Door RL, Dent(s) and scratch(es), Acceptable	0,00

Tyre RR, Deformed / Strained, Acceptable	0,00

Outside rear-view mirror housing L, Scratch(es), Acceptable	0,00

Bumper R, Scratch(es), Repair and paint (complete)	254,16

Bumper trim R, Scratch(es), Smart repair	121,70