Print

macadam vab inspection

TOYOTA RAV4: 1VHC704

Vinnumber:	JTMWRREV60D092149	Versionname:	2.5 VVT-i Hybrid Black Edition CVT
First Registrationdate:	12/11/2018	Fiscalpower:	
Expertise Mileage:	76619	Power Kw:	145
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2819
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

	235/55/18/100 H			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Tyre profile depth FL	4.0
Tyre profile depth FR	4.0
Tyre profile depth RL	4.0
Tyre profile depth RR	4.0
Tyre size FL	235/55 R 18 100 H
Tyre type FL	Summer
Tyre make FL	255
Tyre make RL	255

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2199,41
Wing RR, Scratch(es), Acceptable	0,00

Alloy rim RL, Scratch(es), Acceptable	0,00

Door RR, Scratch(es), Repair and paint (complete)	382,02

Bumper R, Scratch(es), Repair and paint (complete)	254,16

Door panel RR, Scratch(es), Replace	137,00

Alloy rim FL, Scratch(es), Repair and paint (complete)	114,00

Door panel RL, Scratch(es), Replace	137,00

Wing FR, Dent(s) and scratch(es), Repair and paint (complete)	293,21

Luggage compartment cover, Missing, Replace	500,00

Rear window, Scratch(es), Replace	0,00

Bodywork, Not original part, Remove lettering	0,00

Door FL, Scratch(es), Repair and paint (complete)	382,02

Door trim FL, Scratch(es), Replace	0,00

Alloy rim RR, Scratch(es), Acceptable	0,00