

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	174065 KM
File nr. :	1453392	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FRR614 / WV1ZZZ2KZEX039681 /		yr of constructionr :	/
E-File nr. :		First registration :	03/10/2013
VFS-nr. :		Color :	WHITE
Make + Model :	VOLKSWAGEN / CADDY	Fuel type :	DIESEL
Object nr. :	49744	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Besix SA	Co2:	136g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	CADDY VAN B/F 75PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1598
Gear box :	Manueel	Number of places:	
Number of gears:	5	Number of doors:	4
HP:	75	kW:	55
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	NOK [x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK [x]	1.6-2/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	GOODYEAR	Tyre :	OK [x]	>6/	Rim :	[x]	BROKEN DOWN / DAMAGED	/	Hubcap :
Wheel FR :	[x]	GOODYEAR	Tyre :	[x] OK [x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK [x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]	GOODYEAR	Tyre :	OK [x]	2-4/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	M+S
Rear tyre	195	65	R	15	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :		Hubcap :
Wheel RL :		Tyre :	OK /	Rim :		Hubcap :
Wheel FR :		Tyre :	OK /	Rim :		Hubcap :
Wheel RR :		Tyre :	OK /	Rim :		Hubcap :
Wheel RES:		Tyre :	OK /	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] ROOF STYLE/FRONT/LEFT/CENTER CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
5 15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR

[x] REAR MUDGUARD/LEFT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
4 15 LU =72.00 EUR	231.15 EUR		50 %	303.15 EUR

[x] REAR MUDGUARD/RIGHT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR

[x] REAR DOOR/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR

[x] WINDSCREEN/CENTER/LEFT WINDOW DAMAGE

Number	Code	Description	Unit price	Depr.	Total
10	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
10	I 1 i-vab-herstr-02	SUPPL WINDOW REPAIR	29.40 EUR		29.40 EUR

[x] BONNET/CENTER/RIGHT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 25 LU =120.00 EUR	217.56 EUR		50 %	337.56 EUR

[x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	158.85 EUR		50 %	158.85 EUR

Interior

[x]	SEAT FL		BURNT			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR
[x]	BOOT LID IN		OTHER DAMAGES			
			Repair paint - LI	New paint - E	Depr.	Total
1	10 LU =48.00 EUR		200.00 EUR		50 %	248.00 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE		MISSING/INCOMPLETE			
			Repair paint - LI	New paint - E	Depr.	Total
8	5 LU =24.00 EUR		0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	bestelwagen-laadruimte-a-vab-rein-06	CLEANING INTERIOR	23.41 EUR		23.41 EUR

RIM REAR LEFT

			Repair paint - LI	New paint - E	Depr.	Total
9	5 LU =24.00 EUR				50 %	24.00 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
1	1	AFDEKKING		25.00 EUR	50 %	25.00 EUR
5	1	REAR BUMPER		257.40 EUR	50 %	257.40 EUR
8	1	MIRROR COVER		90.00 EUR	50 %	90.00 EUR
9	1	STEEL WHEEL		48.60 EUR	50 %	48.60 EUR

1	2	3	4	5	6	7	8	9	10
360.73	337.56	158.85	303.15	329.40	231.15	238.76	114.00	72.60	88.20
224.23	168.78	79.42	151.58	164.70	115.58	119.38	57.00	36.30	88.20

INNOVATIVE	TRADITIONAL	GENERAL	
175.93	2058.47	0	2234.40
HOG: 0	BG: 3		NA Deprec. 1205.16
			0.00%
			TOTAL 1205.16

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 09:48 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	